## **HG** floor tile treating matrix

Treatment	Porous tiles	Non- porous tiles	(High) gloss tiles
Removal of cement residue	P11 P12	P11 P12	P11
Application of basic protection (impregnation)/ reducing porosity	P13	-	-
Protection of surface against dirt and wear	P14	P14	-
Invisible protection against dirt and staining	P15	P15	-
Regular cleaning	P17	P16 P17	P18
Intensive cleaning, remove protective layer, pre-treatment protective layer	P20	P19 P20	P19 P20
Removal of oil and grease stains	P21 P42	P21	P21







Attention: Transport and store the bottle upright.

• Medical personnel can request the state of the state of

contains a.o.	
anionic surfactants	5-15%
non-ionic surfactants, phosphonates	< 5%
non-ionic surfactants, phosphonates preservation agents: 2-bromo-2-nitropropane- 1,3-diol; perfumes: LIMONENE, LINALYL ACETA TETRAMETHYL ACETYLOCTAHYDRONAPHTHA	TE, ALENES

DANGER H314- Causes severe

skin burns and eve damage. H412- Harmful to aquatic life with long lasting effects. P101- If medical advice is needed, have product container or label at hand. P102- Keep out of reach of children. P280- Wear protective gloves and eye protection. P301+P330+P331 IF SWALLOWED: rinse mouth. Do NOT induce vomiting. P303+P361+P353- IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water for showerl. P305+P351+P338- IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing, P501- Dispose of contents and container in accordance with all local, regional, national and international regulations. Contains: disodium metasilicate CAS: 10213-79-3. Made in The Netherlands by HG International b.v., P.J. Oudweg 41, 1314 CJ Almere, The Netherlands, Tel.: +31 36 54 94 100 UFI: EAKE-5HHQ-G00F-64P4

HG Does what it promises.

UK importer: HG UKI Ltd, Weston Business Centre, Parsonage Road, Takeley, Essex, CM22 6PU. Tel.: +44 (0) 1206 822 744